

FOG OFF DEMISTER

If you have problems with misting of visors or protective eyewear use

FOG OFF DEMISTER

TO

IMPROVE PERSONAL SAFETY

AND

INCREASE OPERATIONAL EFFICIENCY

Just wipe *FOG OFF* on to your visor or protective eyewear to clean away grime and leave the surface mist free.

FOG OFF has been specially formulated for use with PVC.

FOG OFF is non toxic, non corrosive, non irritant, ozone friendly, and entirely safe to use on any visual surface

For further information please contact Respirex on
Tel: 01737 778600 or Fax: 01737 779441

FOG OFF HEALTH AND SAFETY DATA SHEET

APPLICATIONS	FUNCTION/CHARACTERISTICS	HEALTH AND SAFETY
Cleaning	<ul style="list-style-type: none"> • Excellent cleanser • Anti-fogging/anti misting • Anti static 	Non Toxic
Protection against fogging/misting of clear visual surfaces made of PVC	<ul style="list-style-type: none"> • Non smearing • Biodegradable • Persistent • No organic solvents • Pleasant mild odor 	Hydrolysed to inert products if ingested
Polishing	<ul style="list-style-type: none"> • Leaves no marks • Anti-microbial activity • No chemical reaction with rubbers, plastics or glass • Ozone friendly • Near neutral pH, and contains no organic solvents, thus no crazing, erosion or impairment of visor surface clarity 	
<p>NB. For best effect application is made directly to surface first, spread by clean non fragmenting cloth or tissue and gently buff and allow to dry. Application provides a persistent and active layer, a few microns thick which remains attached to the visual surface providing powerful anti fogging properties. The layer will persist for a considerable time unless it is actively dissolved, hot washed or vigorously rubbed off.</p>		